DZ:

FYI...

We are re-revising the Q&A right now...

Eric:

We will send another revised version of the Q&A to you shortly. Thank you for your continued assistance.

George Morino
National Manager
Quality Compliance Department
Product Quality and Service Support
Toyota Motor Sales, U.S.A., Inc.
Tel. 310-468-3392
Fax 310-468-3399

NOTICE: This email message and all attachments transmitted with it are intended solely for the use of the addressee and may contain legally privileged and confidential information. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, copying, or other use of this message or its attachments is strictly prohibited.

If you have received this message in error, please notify the sender immediately by email reply and please delete this message from your computer. Thank you.

----- Forwarded by George Morino/TMS/Toyota on 03/29/2007 01:15 PM -----

Christopher Tinto/WDC/Toyota_NY@TOYOTA_NY 03/29/2007 12:48 PM

To martha voss, Joe Tetherow/TMS/Toyota@Toyota, Bill Kwong/Mobile/Toyota@Toyota, Dana.hargitt@tema.toyota.com, julie_alfonso@toyota.com, John Hanson/TMS/Toyota@TOYOTA, Martha Voss/WDC/Toyota_NY@Toyota_NY, Ming-Jou Chen/TMS/Toyota@Toyota, Michiteru Kato/HINPO/TMC0@TMC0@TMCE@TOYOTA, Shinichiro Ogata/HINPO/TMC0@TMC0, Takezo Oba/HINPO/TMC0@TMC0

As expected (see below), NHTSA opened an investigation today (PE07-016) on the '07 ES350 for "accessory floormat interferes with the throttle pedal." The opening resume alleges 5 complaints and 7 injuries.

See attached for opening resume.

Please let us know if you have any questions.

Regards, Chris

Chris Tinto

Vice President, Technical and Regulatory Affairs, Safety Toyota Motor North America, Inc. 601 13th St. NW Suite 910 South Washington, DC 20005 Phone (202) 463-6824 Fax: (202) 463-8513 email: Chris_Tinto@tma.toyota.com

----- Forwarded by Christopher Tinto/WDC/Toyota_NY on 03/29/2007 03:40 PM ----- Christopher Tinto/WDC/Toyota_NY 03/28/2007 01:05 PM

To martha voss, Joe Tetherow/TMS/Toyota, PR, Mitch Kato, Shinichiro Ogata/HINPO/TMC0@TMC0, Takezo Oba/HINPO/TMC0@TMC0

Today TMA learned that NHTSA will be opening an investigation into the 2007 Lexus ES350, possibly as early as tomorrow. NHTSA has received a total of 10 reports of unintended acceleration, 4 of which reported that a crash had occurred. NHTSA has been looking at this issue closely, and have now come to the conclusion that they believe an improperly installed all weather floor mat may be causing the accelerator pedal to stick in the full or partially depressed position.

NHTSA does not know if dealers or customers are the cause of the situation, but nonetheless, believe it is an issue to investigate further, and will announce the opening of a PE.

It is possible that if an owner places an all weather floor mat over the carpeted floor mat (for a total of two floor mats in place at the same time) the all weather floor mat could slide forward, and cause the accelerator pedal to become stuck in a depressed position. Compounding the issue may be the push button start system, as NHTSA believes owners may not fully recognize how to properly shut the vehicle down in an emergency situation. Both the carpeted floor mat and the all weather floormat are to be used in conjunction with retaining clips (but only one at a time) to prevent the mat from moving about the footwell, and, as designed, the retaining clips cannot retain more than one mat at a time.

The all weather mat also includes an embossed warning, instructing owners not to install over the existing floormats. TMA expects an opening resume to be released in the next day or so, with media coverage to soon follow.

Best Regards, Chris